



ROC L-16 092461

**FIRE EQUIPMENT SALES
AND SERVICE CORPORATION**

ROC L-67 092462

3107 W. VIRGINIA AVE. ★ PHX, AZ 86009-1504 ★ (602)433-2484 ★ Fax (602)433-9626
2921 S. KISH AVE ★ YUMA, AZ 85385 ★ (928) 341-0025 ★ Fax (928) 341-0356
SHOW LOW ★ PINETOP ★ LAKESIDE ★ (928) 532-2292

September 16, 2012

J.B. Akins
Blue Ridge Unified School District #32
1200 W. White Mountain Blvd
Lakeside, AZ 85929

Phone: 928-368-8266 Ext 120
Fax: 928-368-4008
Cell: 928-205-9843
Email: jakins@brusd.k12.az.us

RE: SLM176 Fire Sprinkler Repairs High School West

American Fire Equipment would like to present you with the following proposal for the above referenced facility.

Deficiencies Noted:

- Riser #3 water motor gong rings continuously, WMG was returned to the off position.
- No ITV signage for Mr. Harmon's office.
- FDC for system #1 & #2 are missing signage and is turned in the incorrect position and caps are also missing.
- Fire sprinkler head located near RM #748 is damaged and painted, head shall be replaced.
- Fire sprinkler head located at the O/S dining hall shall be raised approx. 2.5" in order to meet installation requirements.
- Fire sprinkler head located at the O/S RM# 749 shall be raised approx. 1.5" in order to meet installation requirements.
- Painted fire sprinkler heads located in the following areas; (1) storage RM behind registration office across from N. Golden's office, (1) Hall outside N. Golden office, (1) Storage across from Mrs. Bentley's office.

Scope of Work:

- Replace check valve on WMG trim pipe to prevent water to run through alarm trim piping.
- Install ITV sign on door.
- Install signage for the FDC, replace missing caps and rotate FDC to the correct position.
- Section off fire sprinkler system, drain piping, and replace damaged/painted head located near RM# 748, storage RM across from N. Golden's office, hall outside N. Golden office, and storage across from Mrs. Bentley's office.
- Adjust or install hangers to provide adequate height on fire sprinkler drops located at the O/S RM# 749 and O/S dining hall. Customer will have to provide access to overhead piping.